FLR-000733 <sub>TX</sub>	9-NORMAL,NA,100733,KA081 <b>1556</b>	6 120190115 <b>4787</b>	CMCURTXCERTCERTCERTTRDRAMPBUN	
	<section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header><section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header></section-header>	<ul> <li>FUNCTIONAL</li> <li>4.2" LCD CTR STACK SCREEN</li> <li>AM/FM/MP3, 6 SPEAKERS</li> <li>ELECTRONIC PWR ASST STEER</li> <li>ENGINE OIL COOLER</li> <li>INDEPENDENT REAR SUSPEN</li> <li>INTELLIGENT ACCESS W/PUSH BUTTON START</li> <li>LIMITED SLIP REAR AXLE</li> <li>MYKEY®</li> <li>REAR VIEW CAMERA</li> <li>REVERSE SENSING SYSTEM</li> <li>SYNC® WITH APPLINK®</li> <li>TRACK APPS™</li> </ul>	BUCKET SEATS         SAFETY/SECURITY         ADVANCETRAC ESC         AIRBAG-DRIVER/PASS KNEE         AIRBAG-DRIVER/PASS KNEE         AIRBAGS - DUAL STAGE FRONT         AIRBAGS - DUAL STAGE FRONT         AIRBAGS - FRONT SEAT MOUNTED SIDE IMPACT         AIRBAGS - SIDE AIR CURTAIN         INDIV TIRE PRESS MONIT SYS         LATCH CHILD SAFETY SYSTEM         PERIMETER ALARM         SECURILOCK PASS ANTI THEFT         SOS POST CRASH ALERT SYS         WARRANTY         93YR/60,000 BUMPER TO BUMPER         SYR/60,000 POWERTRAIN         SYR/60,000 POWERTRAIN         SYS,000         SAS,355.00         NS/OTHER         \$35,355.00         NS/OTHER         \$36,055.00	fueleconomy.gov Calculate personalized estimates and compare vehicles
	RAMP ONE RK34	TOTAL	MSRP \$37,150.00	1FA6P8CF6K5147648
	RAMP TWO	2-7590 O/T 2 Federal Automobile ne, License, and Title Fees, led. Dealer installed KA081 N I	Whether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance. RA 2X 950 000733 01 08 19	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

1201901154787

