	2A88ABLADJCOVPRCSB10RAMPBUMP	1FMSK8FH9LGC32943 EX	VPLORER	
COMPOSICION CA CA COMPANY IN COMP	ABL ADJ COV PRCS B10 RAMP BUMP ION CORCECR EXPLORER LIMITED 4WD HEELBASE ECOBOOST ENGINE ECOBOOST ENGINE PORTON MARCE NAC POWER OUTLET JP/DOWN DR/PASS WIN HEATED SEATS LIGHT/ILLUM ENTRY A REARVIEW MIRROR R WRAPPED STR WHL E AND AUDIO CTRLS TILATED FRT SEATS TRIMMED SEATS W/ RVPA & DR MEM DID 3RD ROW SEAT /TELE STR COLUMN SEAR SHIFT DIAL HARGING USB PORT(4) E ELECTRNC TMP CTRL AND AUDIO CTRLS 10 0000 0000 0000000000000000000000000	LG C32 XTERIOR AGATE BLACK METALLIC TERIOR SANDSTNE LTHR SEAT SURFACES MERA TEM, 12 SPKR 60™ ASSIST+ NNECT 4GWI-FI ATICS MODEM CESS W/PUSH S CHRGING PAD ERA SYSTEM IG SYSTEM YLESS KEYPAD ILIZATION W/APPLINK®	2943 VITH RSC® ASS KNEE TAGE FRONT SEAT PACT CANOPY® MONIT SYS ETY SYSTEM M A C SYSTEM™ ALERT SYS™	Fuel Economy Fuel Economy MPG Standard SU MPG MPG MPG MPG MPG MPG MPG MPG MPG MPG
	RAMP ONE	TOTAL MSRP \$51,	,325.00	Rollover ★ ★ ★ Based on the risk of rollover in a single-vehicle crash. Star ratings range from 1 to 5 stars (★ ★ ★ ★ ★), with Source: National Highway Traffic Safety Administry www.safercar.gov or 1-888-327-42 1FMSK8FH9LGC32943
	CAK9 CONVOY RAMP TWO ITEM #: 72-0449 O/T 2 This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fee State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above	Whether you decide to lea vehicle, you'll find the choi for you. See your dealer for www.ford.com/finance.	se or finance your ices that are right r details or visit	WARNING: Operating, servicing and maintaining a pass vehicle can expose you to chemicals including engine ex lead, which are known to the State of California to cause cance To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

09/24/2020

