4 CVS-000198 GA 9-NORMAL, N	IB,300198,LM253 <b>1539</b>		SA
VEHICLE DESCRIPTI DESCRIPTION CONTINUE CONT	ON SPORTS FWD ENGER COSPORT S FWD COSPORT S FWD	CERT CERT CERT TRD RAMP BU   MC 4075667   MC 4075667   TERIOR   SMOKE METALLIC   SMOKE METALLIC   SMOKE METALLIC   SMOKE METALLIC   SMOKE METALLIC   TERIOR   ADVANCETRAC® WITH RSC®   ADVANCETRAC® WITH RSC®   AIRBAGS - DUAL STAGE FRONT   DISC/ABS   NECT 4GWI-FI   CISC MODEM   TICS MODEM   AIRBAGS - DUAL STAGE FRONT   AIRBAGS - DUAL STAGE FRONT   AIRBAGS - DUAL STAGE FRONT   AIRBAGS - SAFETY CANOPY®   FRT-PASS SENSING SYSTEM   SIDE AIRBAGS   SIDE AIRBAGS   SIDE AIRBAGS   SOS POST-CRASH ALERT SYS <sup>TM</sup>	MP CAMP BOOK EXFL   File Fuel Economy Small SU/S in The best verified in thest verified in thest verif
			Rollover* * *Based on the risk of rollover in a single-vehicle crash.Star ratings range from 1 to 5 stars (*****), with Source: National Highway Traffic Safety Administ www.safercar.gov or 1-888-327-42
	RAMP ONE   CONVOY     RAMP TWO   ITEM #: 21-1002 O/T 2	TOTAL MSRP\$21,240.00Image: Second systemWhether you decide to lease or finance your vehicle, you'll find the choices that are right for you. See your dealer for details or visit www.ford.com/finance.	WARNING: Operating, servicing and maintaining a passe vehicle can expose you to chemicals including engine ex
	This label is affixed pursuant to the Federal Automobile Information Disclosure Act. Gasoline, License, and Title Fees, State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.		lead, which are known to the State of California to cause cancer To minimize exposure, avoid breathing exhaust, do not idle the vehicle in a well-ventilated area and wear gloves or wash your h For more information go to www.P65Warnings.ca.gov/passenge

02/27/2021

